

Initial layout



Foundation rocks on the right of the photo with the existing school in the background.

The addition will look similar.



Foundation trench dug and rocks being placed.

Note bricks stacked in background.



Foundation trench dug and rocks being placed.



Foundation trench dug and rocks being placed.



Foundation trench dug and rocks being placed.



Mortar being placed between foundation rocks. Note pan for mortar in the back behind the bricks.



Cement being stored in the office.

Other purchased cement is stored at a depot due to inadequate space on-site.



Foundation rocks being delivered outside of the school walls.



Bricks being stored outside of the school walls.



Pile of sand used for mortar. Note door in the background.



Brick walls being placed on top of foundation.



Closer view of brick walls being placed on top of foundation.



Brick walls being placed on top of foundation.
Barrels for water for mortar are in the foreground on the left.



Brick walls being placed on top of foundation.



Brick walls being placed on top of foundation.



Brick walls being placed higher.



Brick walls being placed higher.

Rooms are becoming visible.



Brick walls being placed higher.

Pastor
Tshibuabua's wife
Rose at her first
visit to the
construction.



Pastor Tshibuabua at the construction.

